

2015 - 2016 Road Calls

Date	Bus	Issue	Run	
6/20/2016	232	Oil leak	Route 7	Tightened c
5/1/2016	None			
4/12/2016	235	Overheat	Route 7	Replaced cc
3/1/2016	None			
2/9/2016	217	Hydraulic leak	Route 18D	
2/10/2016	241	Fuel filter plugged	Route 2	
1/18/2016	215	Broken bolt tensioner	Route 6D	Remove bo
1/18/2016	243	Bus died Fuel pump	Route 6	Order fuel p
1/21/2016	241	Cam shaft failure	Route 16	Order cams
12/4/2015	241	Rear axle carrier	Route 6A	
12/18/2015	235	Coolant leak	Route 4A	
11/2/2015	234	Coolant leak.	Route 6	3/4 " hose i
11/23/2015	229	Fuel leak	Route 18D	Leaking fue
10/5/2015	224	Fuel leak	Route 3	Cleaned an
10/13/2015	236	Black smoke	Route 15D	Replaced al
9/3/2015	230	Engine failure	Route 17	May be inje
9/9/2015	243	High temp	Route 6	Replaced pi
9/21/2015	257	Low coolant	Route 12N	Low coolan
9/22/2015	229	Hydraulic leak	Route 1	Replaced h
8/13/2015	224	Hydraulic hose leak	starting from garage	
8/21/2015	214	Engine bad smoke	Route 6D	
8/24/2015	223	Check engine light		
8/26/2015	235	Antifreeze leak		
7/24/2015	238	Coolant leak	Route 1	Replaced u
7/27/2015	226	Over heat	Route 11	Repair fan p

compressor mounting bolts.

controller and air temp sensor

Replaced hydraulic fluid hose.

Cold weather biodiesel

It replaced tensioner

pump

shaft, tappets, gaskets

Replaced hoses to defroster.

under center off bus. Replaced.

! line, tightened line.

d tightened fuel sensor. OK

ll injectors.

ector failure

ins and plug to fan controller

it sensor bad, Cummins has bad coolant sensors in these buses.

ose.

pper rad hose. (Not very old)

plug